

ALERT FIRE BOX 14-7



E-321 ARRIVED HEAVY SMOKE SHOWING



A photograph showing the interior of a building after a fire. The ceiling has collapsed, and debris is scattered on the floor. A wooden staircase is visible on the right. Through the windows, firefighters in yellow gear are visible outside. The scene is dimly lit, with light coming from the windows.

7 MINUTES AFTER ARRIVAL

MAYDAY IS CALLED

2 FIREFIGHTERS ARE DOWN



These are TGI beams,
Before a Fire.



This is what's left after a little
fire impingement.



This is where they should be hanging.



And this is what happens when they are gone.







FIRE LINE DO NOT CROSS

FIRE LINE DO NOT CROSS



TGI beams are used on a lot of modern residential construction.







**THIS COULD BE YOUR NEXT
FIRE.**

BE CAREFUL!!!

